

Indexing

I-DEAS® Tutorials: Milling Projects and Turning Projects

In previous tutorials, you learned how to machine a part using the global-space machining coordinate system as the origin. This tutorial teaches you how to add a 2-, 2 1/2-, and 3-axis machine tool to your setup. You'll also learn how to specify 5-axis positioning.

Do this tutorial if you have a machine tool with more than three axes. If you have three axes or fewer, do the tutorial called Using Multiple Setups.

Learn how to:

- define a machine
- create operation coordinate systems
- pick coordinate systems for operations

Before you begin...

Prerequisite tutorials:

- all tutorials under the Modeling Fundamentals menu
- Introduction to Generative Machining
- Building a Setup Assembly
- Generating In-process Stock and Checking Validity
- Working with Tools and Tool Catalogs
- Picking Holes
- Setting Machining Parameters for Hole-making Operations
- Creating Face Mill and Volume Clear Operations
- Creating Manual Milling Operations

The file you need for this tutorial is distributed with the product. You must copy it into your local directory.

Move to the local directory where you want to copy the file. Then:

In UNIX:


```
cp $SDRC_INSTL/examples/nc/tut_index.arc .
```

In Windows:


```
copy %SDRC_INSTL%\examples\nc\ tut_index.arc .
```

If you can't copy the file, you may have to set up the variable needed to copy from the I-DEAS installation.


```
. sdrc_oadev
```

 If you can't access the file, contact your system administrator. The file may not be installed.


If you did not start I-DEAS with a new (empty) model file, open a new one now and give it a unique name.




Make sure you're in the following application and task:



Set your units to inches.




Import the archive file that contains the parts and tools that you need to complete this tutorial. Importing an archive file can take several minutes. Be patient.



Import Selections form



File Name Input form



The Manufacturing application quits, an informational message is displayed (the message will dismiss automatically), and the archive file is imported.

Import Archive File Status




Be sure to check the List region to be sure that the parts imported properly.



A second informational message is displayed (the message will dismiss automatically) and the Manufacturing application starts.

Create a job.



NC Job Create form

Job Name: Index Machine Bracket


Add the part to the job.



Get

From Bin/Library

Select Part/Assembly form



Recovery Point



Warning!

If you're prompted by I-DEAS to save your model file, respond:



Save only when the tutorial instructions tell you to—not when I-DEAS prompts for a save.


If you make a mistake at any time between saves and can't recover, you can reopen your model file to the last save and start over from that point.

Hint

To reopen your model file to the previous save, press Control-Z.


In the next steps, you'll add a machine instance to your setup and define its origin, orientation, and number of axes. Then you'll add a coordinate system to the machine. By adding a coordinate system, you make it capable of 2, 2 1/2, or 3-axis machining. You'll also modify the settings for the machine to allow 4- and 5-axis positioning.

For brevity, the machine has already been positioned relative to the part for you.



What: Add a machine to the setup assembly.

How:



Add Machine form

 *Get Machine From Bin/Library*


Select Part/Assembly form


 tut_base
 *OK*

I-DEAS Warning

 *Dismiss*

Name form

Name: Machine Assembly
 *OK*



Don't close the Machine Data: Mill, General form.

What: Create a machine coordinate system to specify the origin. The Z axis represents the axis of rotation for the tool spindle.

How:

Machine Data: Mill, General form



Type: Mill



Create MCS

Pick anywhere on the machine instance.



Origin



Between



V1



V6



X Axis



E9



Arrow direction: Yes or No.




Z Axis



E7



Arrow direction: Yes or No.



 Don't close the Machine Data: Mill, General form.

What: Pick the coordinate system to define it as the origin, or program zero.


How:

Machine Data: Mill, General form



Pick MCS

1 origin of coordinate system



*General
Kinematics*



4th Axis—On



*Head
Table*



5th Axis—On




*Head
Table*



OK


Recovery Point



*File
Save*


After you've set 4- or 5-axis positioning, you must specify the positions to where the machine will rotate. You define these rotations by adding operation coordinate systems relative to the surfaces that are to be machined. The orientation of the Z axis represents the position of the tool spindle at each rotation.

In the next steps, you'll create three operation coordinate systems that represent three rotations of the machine tool.



What: Create an operation coordinate system for the first rotation. This coordinate system will be used to machine the pocket nearest to it.

How:



1 anywhere on the part

 *Origin*

2 V4

 *X Axis*


3 E7

 Arrow direction: *Yes or No.*


 *Z Axis*

4 E11

 Arrow direction: *Yes or No.*




Result



What: Create a second operation coordinate system.
This coordinate system will also be used to machine a pocket.

How:



1 anywhere on the part

 *Origin*

2 V3

 *X Axis*


3 E7

 Arrow direction: *Yes or No.*


 *Z Axis*

4 E9

 Arrow direction: *Yes or No.*




Result



What: Create a third operation coordinate system.

How:




1 anywhere on the part




2 V17

3 V15



 Continue creating the coordinate system on the next page.



What: Continue creating the coordinate system.

How:

X Axis

4

E11


Arrow direction: Yes or No.

Y Axis

5

E38


Arrow direction: Yes or No.



Recovery Point


File
Save

Result




In the next steps, you'll create three operations, each with a separate index position. To reach the selected surfaces, you'll pick a different coordinate system for each operation.

When you pick a coordinate system for an operation, the toolpath data is generated relative to it.




What: Create a volume clear operation.

How:



OpGroup Specification form

Name: Machine Cavity A




Operation Selection form

Category: Milling

Type: Volume Clear

Create

 Don't close the Operation Specification form.

What: Pick the coordinate system for the operation.

How:

Operation Specification form




Coordinate System List form



MK2



Dismiss



Things to notice

When you select MK2, the coordinate system is highlighted on the screen.

For volume clear operations, pick the coordinate system before selecting the surfaces. When a setup doesn't contain a stock, you must define one by specifying its shape and size. The software calculates the size of the stock in relationship to the current MCS. If you didn't pick the proper MCS before defining the stock, you may receive an error indicating that your values are reversed or incorrect.

What: Name the operation and select the surfaces to be machined.


How:

Operation Specification form

Name: Volume Clear Cavity A



1 F13 (double-click to select the cavity)



 Don't close the Stock Specification form.

What: Define the stock.

How:

Stock Specification form



Stock Top

1 F16



accept if necessary



Stock Bottom

2 F13




accept if necessary




With XY Offset of: .25



OK



 Don't close the Operation Specification form.

What: Use a 1/2" diameter end mill to machine the cavity.

How:

Operation Specification form



Cutting Tool Specification—Mill form




Item Selection form



1/2" dia end mill



 Don't close the Operation Specification form.

What: Specify the cut pattern as *Spiral In*. Then set the cutting passes as .25" beyond the boundary of the stock.

How:

Operation Specification form



Machining Parameters form



Cut Pattern



Axial Depths...




Maximum Depth Of Cut: .5



OK




OK

 Don't close the Operation Specification form.

What: Generate the toolpath.

How:

Operation Specification form



Things to notice


The engage and retract motions are parallel to the machining coordinate system that you selected for the operation. The toolpath also forms a spiral-in pattern and its cut passes extend beyond the edge of your defined stock.

Recovery Point



What: Create a new opgroup and operation by copying the current opgroup. When you copy the operation, its tool and machining parameters are copied also. You'll only have to pick different surfaces and a new coordinate system to create a toolpath.

How:



NC Job Planning form




Machine Cavity A



Deselect *Machine Cavity A* by pressing the Control key and selecting *Machine Cavity A*.



 Don't close the NC Job Planning form.

What: Modify OpGroup-2, then modify Operation-2.

How:

NC Job Planning form



OpGroup Specification form

Name: Machine Cavity B



Operation-2



Operation Specification form

Name: Volume Clear Cavity B



Don't close the Operation Specification form.

What: Pick the coordinate system for the operation.

How:

Operation Specification form




Coordinate System List form




MK3



Dismiss



 Don't close the Operation Specification form.

What: Pick the surfaces to be machined.

How:

Operation Specification form




Stock Specification form



Deselect All

1 F4 (double-click to select the cavity)



Don't close the Stock Specification form.

What: Define the stock.

How:

Stock Specification form



Stock Top



Deselect All

1

F18



Stock Bottom




Deselect All


2

F10



OK

 Don't close the Operation Specification form.



What: Generate the toolpath.

How:


Operation Specification form



I-DEAS Warning




OK



Things to notice

Because you copied the tool and machining parameters from the previous operation, this toolpath appears similar.

Recovery Point




File

Save


What: Create an opgroup, then a manual operation.

How:



OpGroup Specification form

Name: Machine Face C




Operation Selection form

Category: Milling

Type: Manual

Create

 Don't close the Operation Specification form.

What: Pick the coordinate system for the operation.

How:

Operation Specification form




Coordinate System List form




MK4



Dismiss



 Don't close the Operation Specification form.

What: Pick the canted surface to be machined.

How:


Operation Specification form



Name: Manual Mill Face C




1 F20



Surface Selection form



Dismiss

 Don't close the Operation Specification form.


What: Pick the first guide curve that defines the path of the tool. The arrow indicates the cutting direction of the tool, and the start point and entry of the toolpath.

How:

Operation Specification form



Machining Parameters form



Guide Curve Sets form




Change arrow direction, if necessary.



Don't close the Guide Curve Sets form.

What: Pick the second guide curve. The arrow indicates the cutting direction of the tool and the exit.

Guide Curve Sets form



Guide Curve Sets form



Change arrow direction, if necessary.



OK



Don't close the Machining Parameters form.

What: Define an axial depth of zero so the tool contacts the surface of the part.

How:

Machining Parameters form



Project Onto—Off



Single Pass with Z Translation of: 0



Don't close the Machining Parameters form.

What: Specify an in-plane entry and an in-plane exit. Also set the maximum drive length for region connections to 100 percent of the tool diameter so that the tool retracts between cuts.

How:



Cut...

Entry...



Entry Type: In Plane



Angle: 0



Entry...

Exit...



Exit Type: In Plane



Angle: 0



OK



Don't close the Operation Specification form.

What: Use a 1" diameter end mill to machine the surface.

How:


Operation Specification form




Cutting Tool Specification—Mill form




Item Selection form




 Don't close the Operation Specification form.

How:



The entry and exit of the toolpath follow the direction of the arrows on the guide curves that you selected earlier.

Recovery Point



File
Save

Tutorial wrap-up

You've completed the Indexing tutorial.